


Assembly Guide

RJ45 Plugs


A. Plug



B. Insert

C. Crossing insert

1) Cat.6A plug components.



2) Cut the cable jacket 25mm.
Make sure not to hurt the 8 wires.



3) Cut the crossing layer of 8 wires



4) Put the 8 wires into crossing insert down according to 568B wiring.



5) Put the 8 wires into insert down



6) Cut the 8 wires outside the insert.



7) Put the cable into the plug.



8) Crimp the contacts with a crimp machine.



9) Patch cord assembly is finished.



10) Finish modding and make sure your cable has a professional appearance.