



NOTE: ALL MATERIAL COMPLIANT ROHS STANDARD

REVISION INFORMATION			
Rev.	Rev. Date	Modified By	Brief Description
1.0	2022.04.07	Cheng Pu	RXLR 3P M/F Balanced Audio Microphone Cabl



Connection



ELECTRICAL TESTING

1. CONDUCTOR RESISTANCE: ≤5Ω 300V DC

Item #	Length(L)
203100	3FT / 915 ± 30 mm
203101	6FT / 1830 ± 30 mm
203102	10FT / 30500 ± 40 mm
203103	15FT / 4570 ± 80 mm
203104	25FT / 7620 ± 80 mm
203105	50FT / 15240 ± 100 mm
203107	100FT / 30480 ± 150 mm

NO.	PART NAME	SPECIFICATION DESCRIPTION	QTY	UNIT
③	Jack	XLR 3P Female	1	1
②	Plug	XLR 3P Male	1	1
①	Cable	10/0.10 CCS*2C+10/0.10CCS, OD:5.0 mm	1	1

DRAWN BY Mr. Kuo	DATE: 2022.02.23	DESCRIPTION: XLR 3P Male/Female Balanced Audio Microphone Cable
CHECK BY Mr. Liu	SHEET 1 of 1	ITEM NO. 203100/1/2/3/4/5/7
APPROVED BY John Lee	SCALE 2:1	REV. 00 UNIT: mm